

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

Table of Contents

DNAPL Behavior in Fractured Rock –Transport Facilitated by Pickering Emulsions Bernard Kueper, A. Roy-Perreault, and M.R. West	1
Geophysical Characterization of Fractured Rock Aquifers: Accounting for Scale Effects and Putting Hydrology into the Geophysics Fred Paillet.....	14
NGWA Distinguished Darcy Lecture: Recent Advances in Characterizing Ground Water Flow and Chemical Transport in Fractured Rock: From Cores to Kilometers Allen Shapiro.....	27
Field-Scale TCE Oxidation in Sedimentary Bedrock: KMnO₄ and BR⁻ Tracer Test Results and Extended Pilot Design Michael J. Gefell, Kenneth L. Sperry, James R.Y. Rawson, and Edward Kolodziej	28
Field Testing of Nanoscale Zero-Valent Iron Particle Technology for Insitu Ground Water Treatment in Fractured Bedrock F. Gheorghiu, L. Walata, R. Venkatakrisnan, W. Zhang, and R.E. Glazier.....	30
Remediation of a Chlorinated Solvent Contaminated Site Using Steam Injection and Extraction David Parkinson and Norm Brown.....	32
Implementing RF Heating in Fractured Bedrock to Remediate TCA DNAPL H. Jean Cho, R. Joseph Fiacco, John W. McTigue, Alicia R. Kabir, Karen L. Brody, and Ray Kasevich	34
Remediation of Tetrachloroethene in Fractured Sandstone: A Case Study in Initial Successes and Long-Term Technological Barriers to Timely and Cost-Effective Closure Vasanta Kalluri, Kevin Brehm, and Jeanne Tarvin.....	44
Remediation of a Clay and Fractured Rock Source Area Using Vacuum Extraction and Bioremediation Gregory L. Carter and Roasann Kryczkowski.....	57
Art in-Well Air Stripping Technology: Remediation in Fractured Rocks Completed in Months Marco M. Odah, Steve Pucke, and Chuck Reed	59
Blast-Fractured Enhanced Permeability Remediation System at Modern Landfill, Your, Pennsylvania: A Five-Year Update J.R. Smerekanicz, J.J. Elsea, F. Gheorghiu, and M.C. Pedersen	68
Characterizing a DNAPL Site in Karst Terrain: Implications for Remediation Keith A.White, David S. Lipson, Kurt Paschl.....	78
Evaluation of Successful MTBE Remediation in the Stockton Formation Craig A. Kunz and Shawn McCune	80

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

Remedial Strategies Applied to a Fractured Bedrock Contaminant Plume at the University of Connecticut Landfill Study Area John R. Kastrinos, Richard P. Standish, James Pietrzak, Susan Soloyanis, Mitretek F. Peter Haeni, and Carole D. Johnson	89
Using Major Ions to Support the Demonstration of Hydraulic Containment in a Fractured Bedrock Aquifer Steven P. Sayko, William F. Daniels, and Richard J. Passmore	100
Technical and Regulatory Challenges Resulting from VOC Matrix Diffusion in a Fractured Shale Bedrock Aquifer Kenneth J. Goldstein, Andrew R. Vitolins, Daria Navon, Grant A. Anderson, Stephen P. Wood, Beth Parker and John Cherry	115
Technical and Regulatory Considerations for DNAPL Remediation in Complex Hydrogeology Beth A. Moore and Dawn S. Kaback.....	127
Observations from Several Bedrock Remediation Programs in EPA Region 1 (New England): A Monitoring Perspective William Brandon, Michael J. Daly, Charles Franks, John A. Lough, Steve Mangion, and Ernest Waterman	128
LNAPL Behavior in Fractured Rock: Implications for Characterization and Remediation Paul E. Hardisty, John Roher, and Jane Dottridge	129
Bedrock: From Foe to Friend – A Case History of Investigation and Remediation in Fractured Bedrock from 1979 Through 2003 Ian M. Phillips and Michael D. Walters.....	136
Fractured Bedrock Aquifer Hydrogeologic Characterization for a Bioaugmentation Pilot Study Paul Jeffers and Veryl Wittig	148
Fractured Rock Transmissivity Estimates From Oscillatory Slug Test Data Jeffrey R. Hale	158
Ground Water in Fractured Bedrock: A Water Supply Approach Raymond W. Talkington.....	160
Pumping Test Analysis in a Fractured Crystalline Bedrock H. Jean Cho, Matthew H. Daly, and R. Joseph Fiacco, Jr.	161
A New Visual Synthesis Tool for Transient Test Data Christian Enachescu and John Wozniwicz	173
Gas Injection Tests Gonzolo Pulido and Thomas P. Ballesteros	186

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

Large Drawdown Slug Tests Gonzalo Pulido, Thomas P. Ballestero, and Nancy E. Kinner	203
Assessing the Potential for Saltwater Intrusion in a Coastal Fractured-Bedrock Aquifer Using Numerical Modeling Thomas J. Mack.....	220
Vertical Distribution of Hydraulic Conductivity in Cambrian Sandstones in South-Central Wisconsin Kenneth R. Bradbury, David J. Hart, David L. LePain, Beth L. Parker, Diane C. Austin, and Jessica R. Myer	222
Hydrogeology of Granitic Terrains: A Comprehensive Study of Minho Region (Northwestern Portugal) A.S. Lima and M.O. Silva.....	223
Vertical Cross Connection in a Single borehole: A Case Study in Fractured Sandstone Sean N. Sterling, Beth L. Parker, John A. Cherry, John W. Lane, John H. Williams, and F. Peter Haeni.....	224
Characterizing the Hydraulic Properties of Fractured Bedrock – A Fractured Sandstone Example Edwin A. Romanowicz, Fred Paillet, Andrew Reeve, Matt Becker, Gregory Baker, and David Franzl.....	226
Road Salt Behavior as a Dense Aqueous Phase Liquid in Fractured Bedrock Joshua Katz	228
Characterization and Monitoring Techniques for Solvent Contamination within Fractured Bedrock Scott Pearson and Brian Murphy	239
Assessing the Role of Structural Geologic Elements in Aquifer Hydraulics and Plume Migration Matthew Erbe, Robert Keating, Connie Travers, Lonnie Norman, William Cutler, and Todd Martin.....	240
The Regional Bedrock Structure at Loring Air Force Base, Limestone, Maine; The Unifying Model for the Study of Base-Wide Ground Water Contamination Peter Thompson, Peter Baker, Scott Calkin, and Peter Forbes.....	252
Hydrogeologic Framework Based on Van Houten Cyclic Stratigraphy and Gamma-Ray Logging, Naval Air Warfare Center, West Trenton, New Jersey Pierre Lacombe, Jeffery M. Dale, and Jean C. Lewis-Brown.....	266
Elevated Naturally-Occurring Radioactivity in Ground Water from Three Fractured Bedrock Settings: Implications for the State of Vermont Jonathan Kim and Laurence Becker.....	269

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

Geochemical and Isotopic Characterization of a Local Catchment within Crystalline Basement in Benin/West Africa Thorsten Fass and Barbara Reichert.....	271
Isotopic and Chemical Characterization of Water from Mine Pits and Wells on the Mesabi Iron Range, Northeastern Minnesota, as a Tool for Drinking Water Protection James F. Walsh	280
Time Lapse Geophysical Monitoring in Fractured Rock Aquifers Carole Johnson	295
Lessons Learned from Bedrock Blast Fracturing and Bioremediation at a Superfund Landfill Stuart C. Pearson, Brian B. Johnson, Nelson Walter, and Richard Galloway	308
An Integrated Approach to Contaminant Mass Removal from Vadose and Saturated Fractured Bedrock Brian Vanderglas and Brian Murphy	310
Evaluating the Performance of a Seepage Barrier Constructed with Coal Combustion Product Grout to Reduce the Loss of Ground Water Seeping into a Former Coal-Mining Shaft Nathaniel Warner, Matthew Erbe, Leonard Rafalko, Paul Petzrick, and Gary Fuhrman	315
Toward an Improved Risk Assessment of the Contaminant Spreading in Fractured Underground Reservoirs Christos Tsakiroglou, Maria Theodoropoulou, Vaggelis Karoutsos, Knud Erik S. Klint, Peter Gravesen, Catherine Laroche, Laurent Trenty, and Pierre LeThiez	329
Importance of Flowmeter Logging for Aquifer Characterization at Contaminated Bedrock Sites Carole D. Johnson, John H. Williams, and Frederick L. Paillet.....	331
Characterization of Heterogeneous Flow Zones in a Crystalline Aquifer with Borehole Logging and Cross-borehole Flowmeter Experiments T. Le Borgne, F.L. Paillet, and O. Bour.....	332
Evaluating a Conceptual Model for Distant Coal Tar Migration by Bedrock Fracture Flow Lynette B. Mokry, George M. Thomas, P.G., and Michael J. Gefell P.G., Blasland, Bouck and Lee Inc.	339
Use of the In Situ, Troll 9000 to Locate Fractures Contributing to Ground Water Flow in Bedrock Wells R. Sernoffsky and G. Robbins, R. Mondazzi.....	341
An Innovative Approach to Investigation of an MTBE Plume in Fractured Bedrock Timothy S. Burke, Sarah A. Czajka, and David C. Raymes.....	350

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

Imaging Channelized Flow in Bedrock Fractures using Ground Penetrating Radar Jennifer Talley, Matthew Becker, Gregory Baker, and Nicholas Beyrle.....	352
Hydrochemical Facies Analysis of 1,1,1-Trichlorethane and its Degradation Products in Fractured Bedrock H. Jean Cho, R. Joseph Fiacco, Mathew H. Daly and John W. McTigue	354
Examination of the Relationship of Rock Structure to Ground Water Flow in a Fractured Limestone Aquifer William Brandon and Robert Hoey	366
Aqueous Chemistry of Various Hydrogeologic Units of the Fractured Bedrock Aquifer in the North Carolina Piedmont Jack L. Stutts.....	368
Utility of Rock Core for Characterizing Contamination in Fractured Sedimentary Rocks Beth Parker	370
Hydrogeologic Investigation of VOC Contamination in Bedrock Using Mass Flux Analysis: A Case History Richard K. Eby, Robert E. Zimmermann, Michael T. Paczkowski, and Terence Regan.....	372
Effectiveness of Monitored Natural Attenuation at Predicting In-Situ Biodegradation in a TCE Contaminated Granitic Bedrock N.E. Kinner, M. Mills, T. Eighmy, T. Ballestero, J. Coulburn, and L. Tisa	383
Evidence of Biodegradation at a DNAPL Contaminated Fractured Bedrock Field Site Using Stable Carbon Isotopes Michelle M.G. Chartrand, Penny L. Morrill, Georges Lacrampe-Couloume, Kevin T. Finneran, Paula Chang, Peter Zeeb, and Barbara Sherwood Lollar	385
Natural Attenuation of Solute Plumes in Bedded Fractured Rock Michael West and Bernard Kueper	388
Microfracture Geochemistry as an Indicator of Terminal Electron Accepting Processes in TCE-Contaminated Bedrock T. Eighmy and J. Spear, W. Bothner, J. Coulburn, L. Tisa, and N. Kinner	402
Measuring Mass Balance, Oxidant Half-Life, and Treatment Efficiency: Field-Scale PCE Oxidation Using KMnO₄ in Fractured Phyllite Michael J. Gefell, Bernard H. Kueper, Kenneth L. Sperry, and James R.Y. Rawson	404
In-Situ Chemical Oxidation of Volatile Organic Compounds in a Fractured Bedrock Aquifer Paul D. Rohde and Cynthia R. Butler.....	406
Fractured Crystalline Bedrock Ground Water Remediation of Dissolved TCE via Sodium Permanganate Solution Injection and Re-circulation William F. Simonsa nd Paul D. Steinberg	417

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

In-Situ Remediation of Fractured Bedrock DNAPL Sites Using Chemical Oxidation J.S. Konsuk, L.K. MacKinnon, E.D. Hood, and E.E. Cox.....	425
Implementation of In-Situ Chemical Oxidation in Fractured Bedrock Timothy J. Pac, Richard Lewis, R. Joseph Fiacco, Jr., and Edwin Madera	437
In-situ TCE Oxidation Using Potassium Permanganate in the Columnar-Jointed Preakness Basalt of New Jersey Brian A. Blum, Bill N. Stephanatos, Michael E. Poland, and Gary M. Fisher.....	439
In-Situ Chemical Oxidation Using Permanganate for Remediation of Chlorinated VOCs in a Fractured Shale Matrix Andrew R. Vitolins, Kenneth J. Goldstein, Daria Navon, Grant A. Anderson, Stephen P. Wood, Beth Parker and John Cherry	453
In-Situ Chemical Oxidation with Sodium Permanganate in a fractured Crystalline Bedrock Aquifer: A Case Study Charles D. Race and Liyang Chu.....	462
Multi-Method Geophysical Approach for Characterizing a Deep Fractured Bedrock Aquifer, Anniston Army Depot, Anniston, Alabama Brian S. Murray and Matthew B. Vest.....	464
Ground Water Exploration by VLF Techniques: A Case Study in Granitic Terrains of Northwestern Portugal Luis Macedo and Alberto S. Lima	479
Hydrogeological Exploration by Electrical Resistivity Surveys in Hard Rocks of Montalegre Area (Northern Portugal) Alcino Canas, Alberto S. Lima, and João Fonseca.....	481
Hydrogeology of the Châteaguay River Transboundary Aquifers, Canada – USA M. Nastev, C. Lamontagne, T. Tremblay, F. Hardy, M. Lamothe, R. Leferbvre, A. Croteau, M. Lavigne, D. Blanchette, D. Paradis, and N. Roy	483
The Use of Borehole Geophysics to Optimize Bedrock Drilling Locations Gene Schragger, Brian F. Thomas, and Mark Blackey.....	487
Analysis of Geophysical Logs at North Penn Area 6 Superfund Site, Lansdale, Montgomery County, Pennsylvania Randall W. Conger and Dennis J. Low	492
Integrated Characterization of a Naturally Fractured Igneous-Metamorphic Ground Water System for Open Pit Mining Operations Bob Will.....	506
Use of Fracture Fabric Analysis Facilitates Well Siting and Assessment of Contaminant Distribution in Bedrock Daniel Folan, Dennis Albaugh, A. Curtis Weeden, and Mark Gerath	508

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

Fracture Characterization Using Borehole Radar: Computer Simulation and Field Calibration Lanbo Liu, Fred Day-Lewis, and John W. Lane	523
Determining Geological Structures in Fractured Bedrock from the Surface for Aquifer Characterization: A Practical and Inexpensive Approach Italo Alfredo Guagnelli and Scott Ian Koolik.....	525
Hydrologic and Geophysical Investigation of Bedrock Observation Wells at the University of Maine Eric Rickert, Andrew Reeve, and Frederick L. Paillet	532
Systemic Characterization of a Bedrock Aquifer in Coastal New England John Alastair Lough	545
Conceptual Flow Model and Ground Water Characterization Strategy for Sedimentary Bedrock Sites Andrew Michalski	547
Thermal Hydrosystem of Gerês Spa (Northwestern Portugal): Proposal of a Conceptual Model Alberto S. Lima.....	549
Characterization of Fractured Rock to Develop Conceptual Models of Ground Water Flow and Transport of Mercury Philip T. Harte, James R. Degnan, Stewart F. Clark Jr., Margaret Bastien and Thomas J. Mack.....	551
Evolving Conceptual Models and Monitoring Well Reconstruction in the Passaic Formation in New Jersey John N. Dougherty, Andrea Soo, and Robert M. Alvey.....	553
Using Fractran Fracture Flow Modeling in Tandem with Modflow to Assist in the Development of Wellfield Protection Zones for Municipal Wells in Bedrock T.K. Wiesel, G.G. Violette, and S.T. Hamilton	566
Evaluation of Various Slab-Fissured Models for Characterization of Fractured Rock Aquifers: Eastern Pennsylvania Joseph A. Fishcer, James G. McWhorter, and Joseph J. Fischer	577
Control of Fractured Bedrock Structure on the Movement of Chlorinated Volatile Organics in Bedrock and Overburden Aquifers, Newark Basin of New Jersey Robert M. Bond and Katherine E. Linnell.....	586
Historical and Present Site Conceptual Models for a Fractured Bedrock Superfund Site in New York State Lisa G. Campbell, Susan E. Schofield, P.G., Kristen E. Carpenter, and John N. Dougherty	595

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791



fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

Fractured Bedrock DNAPL/Dissolved Phase Plume Conceptual Model Development at the Eastland Woolen Mill Superfund Site, Corinna, Maine Scott Calkin, Peter Thompson, Peter Baker, Scott Acone, and Ed Hathaway.....	597
Structural Characterization and Passive Remediation of NAPL in Fractured Bedrock at a Former MGP Site: Mechanicville, New York Michael Gutmann, Eriko Fujita, Beth Guidetti, and Tracy Blazicek.....	610
Use of Vertical Gradient to Compensate for Disparate Completion Depths when Characterizing Horizontal Flow Direction in Stacked Fractured Aquifers During an MTBE Investigation, Maripos County, California William Ackland and Herman Schymiczek.....	622
Monitored Natural Attenuation of Chlorinated Solvents in Fractured Bedrock as a Selected Remedy for Ground Water at a Superfund Site Rebecca Lindeman and David S. Lipson.....	636
Characterization of Three Water Types in a Fractured Schist, High Arsenic, Watershed in Maine Gail Lipfert and Andrew Reeve.....	638
Development of a Conceptual Field Scale Flow Model in a Fractured Bedrock Aquifer Bibhuti Panda.....	647
NAPL Removal from Fractured Bedrock Using (SPTT™) Non-ionic Surfactants Successful Ground Water Remediation Cases George A. Ivey.....	649
Hydraulic Properties of Granitic Fracture Skins and Their Effect on Solute Transport Terence T. Garner and John M. Sharp, Jr.....	664
The Approach to Understanding and Controlling Contaminant Fate and Transport on the U.S. Department of Energy's Oak Ridge Reservation, Tennessee (USA); A Review of Status and Future Challenges Thomas O. Early, Phillip M. Jardine, and Richard H. Ketelle.....	679
Analysis of X-ray Computed Tomography Scans to Characterize and Measure the Surface Roughness of Natural Rock Fracture Samples Clark Thompson.....	681
Steam Injection into Fractured Limestone at Loring Air Force Base Eva L. Davis, Gorm Heron and Steve Carroll.....	683
Using Tracers to Understand Advection, Dispersion, and Diffusion in Fractured Rock Matthew W. Becker.....	685
Innovation Approach for Hydraulic Containment of PCB Contamination in Fractured Bedrock Jack Guswa.....	695

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

Successful Application of Technical Impracticability for Achieving a Cost Effective Remedy for DNAPL in Deep Fractured Limestone/Dolostone at a Superfund Site David W. Lay, Michael J. Gefell, Bernard H. Kueper, William T. McCune, and Curt Christensen	699
Evaluating Innovative Bioremediation Technologies and Successful Pilot Test Performance Tess Rottero, Craig Walmsley, and Oliver Kohlen.....	702
Ethanol Biostimulation and Bioaugmentation of VOC-Impacted Deep Bedrock Aquifer Christopher J. Voci, Michael S. Kozar, and Roy S. Blickwedel.....	710
Fracture Characterization at a Bedrock Bioremediation Site in New Hampshire Stanley S. Sadkowski, Wallace A. Bothner, Jean Benoît, Francis S. Birch and José Escamilla-Casas.....	716
Enhanced Bioremediation of DNAPL in a Fractured Limestone Aquifer: Bench Test Results Neal D. Durant Eric D. Hood, Sandra M. Dworatzek, Jeff Roberts, Keith B. Rapp, Terry Etter, and William H. Anthony.....	718
Combined Use of Borehole Geophysics and Packers to Site Potable Wells in a Contaminated Area Aaron Green, John W. Lane, Jr., Carole D. Johnson, John H. Williams , Remo A. Mondazzi, Peter K. Joesten.....	720
An Integrated View of Ground Water Flow Characterization and Modeling in Fractured Geologic Media Mingyu Wang and Rob Earle	736
Fracture Network Characterization for Studies of Retention Processes at the Äspö Hard Rock Laboratory Thomas Doe and Jan Hermanson, Peter Andersson, and Anders Winberg.....	750
Application of the Fractured Bedrock Toolbox at Multiple Sites in New England R. Joseph Fiacco, Jr., Matthew H. Daly, and John C. Drobinski.....	764
Hydrogeological Characterization for Siting Geothermal Wells in Fractured Bedrock at Bronx Zoological Park, Bronx, New York Dennis Askins and Alex Posner	777
The FLUTE Multilevel Ground Water Monitoring System Used for Study of a Contaminated Dolostone Aquifer John Cherry, Beth L. Parker, Christopher M. Turner, Leanne S. Burns and James H. Plett, and Carl E. Keller.....	778
Ground Water Sampling Method Comparison: Low-Flow and Passive Diffusion Bag Sampling Results for Volatile Organic Compounds in Fractured Metamorphic Bedrock Thomas R. Eschner and David Dinsmore.....	780

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Home

Program

Table of Contents

From Low-Flow Sampling to Passive Diffusion Bag Samplers: The Evolution of Volatiles Characterization in a Triassic Shale Aquifer Matthew P. Lesley and Raymond E. Lees	793
How to Locate and Flow Test, Every Major Fracture in a Borehole in One Hour Carl Keller	801
Multipurpose Packer System Gonzalo Pulido, Thomas P. Ballesterio and Nancy E. Kinner	809
Unpredictable Pattern of Road Salt Contamination in Private Wells Demonstrates Crucial Role of Interconnections Joshua Katz	824
Use of Angled Drilling Techniques to Characterize Fractured Crystalline Bedrock and Minimize Migration of Suspected Non-aqueous Phase Liquids (NAPL) David Finney, Jeffrey Hershberger, and Peter Nangeroni	825
Using Minimal Impact Deep Drilling Techniques in a DNAPL Impacted, Fractured Rock Aquifer Matthew B. Best and Brian S. Murray	834
Investigation of the Impact of Fracture Intersection on Solute Transport in Fractured Carbonate Catherine Ledoux, René Therrien, Kent Novakowski, Donna Kirkwood	836
Large-scale Solute Transport Modeling in Discretely-Fractured Porous Media Guillaume Kenny, René Therrien, and André Fortin, Kent Novakowski	848
Multiscale Site Characterization for the Numerical Mapping of NAPL Migration Pathways in Contaminated Fractured Igneous Rocks: A Case Study in Northern Spain Knud Erik S. Klint, Peter Gravesen, Catherine Laroche, Laurent Trenty, Pierre LeThiez, and Christos Tsakiroglou	861
Ground Water Flow Simulation of a Glacial Aquifer and its Implication for the Management of University of Connecticut Water Supply System During Drought Periods Farhad Nadim, Jeffrey J. Starn, and Amvrossios C. Bagtzoglou	863
Discrete Analytic Domains: A New AEM Formulation for Modeling Anisotropy and Heterogeneity Charles Fitts	867
Statistical Modeling of a Non-Parametric Data Distribution to Determine an Exposure Point Concentration during Risk Assessment Adam P. Chen and Joan V. Gonzalez	880

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791



fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org

2004 U.S. EPA/NGWA Fractured Rock Conference: State of the Science and Measuring Success in Remediation

September 13-15, 2004
Portland, Maine
Holiday Inn by the Bay



Discrete Fracture Network Modeling: Current Status and Future Trends
William S. Dershowitz, Paul R. Lapointe, and Thomas W. Doe 882

Ground Water Flow and Contaminant Transport Modeling of Fractured Bedrock Aquifer with Solution Channels at a Southeastern Pennsylvania Superfund Site
Henry He and Andrew H. Thalheimer 895

A Simple Analytical Model for Heat Flow in Fractures – Application to Steam Enhanced Remediation Conducted in Fractured Rock
K.S. Novakowski, K.M. Stephenson, E.L. David, S. Carroll, G. Heron, and K. Udell 908

Determining the Average Fracture Spacing Between Fractures and Planning of the Best Paths for the Wells in a Field Located in the Middle Magdalena Basin-Colombia
Roa Leonardo and Peñaloza Melendez Jorge 909

Natural Attenuation of Dissolved Petroleum Components in Fractures Crystalline Rock: Results from Field Experiments at Äspö Hard Rock Laboratory, Sweden
Ola Landin, Sten Berglund, Lotta Hallbeck, Sara Eriksson, Katrina Abrahamsson, Tobias Ankner, and Lars-Gunnar Karlsson 924

601 Dempsey Rd.
Westerville, OH 43081

phone:
800.551.7379 toll free
or
614.898.7791

fax:
614.898.7786

email:
ngwa@ngwa.org

www.ngwa.org