Jordan River & Midvale Slag **Beneficial Use**

Presented by

Marian Hubbard-Rice Salt Lake County Watershed Planning

> Erna Waterman U.S. EPA Region 8











History of Midvale Slag



446-acre is located 12 miles south of Salt Lake City 1871-1958 Smelters and Mineral Processing












History of Midvale Slag



Treated ores from Bingham Canyon and other mines Lead and arsenic were primary products












History of Midvale Slag



1984-Studies determine groundwater and soils are contaminated with metals 1990-EPA initiated cleanup actions to address immediate threats at the site 1991-Listed on EPA National Priorities List (NPL)

2006-EPA issued ESD that changed land use restrictions to accommodate multiple land use and created an approach for riparian management












United States Geological Survey (USGS)



2008-EPA hires USGS:

- Create a 2D model to evaluate the river's velocities and also where the river is constrained, eroding, and migrating out of current channel
- Borehole sample map to avoid pockets of slag during construction









Sheet Pile Dam-Grouted Boulder Structure





EPA replaced damaged sheet pile dam

- 2008-Sheet pile dam was dangerous and replaced with a grouted boulder structure
- 2008-Three spur dikes installed east (Midvale) bank of river to redirect flow to away from bank
- 2009-Secondary high flow channel created due to scouring from high flows












Sheet Pile Dam



Grouted boulder structure becomes a kayakers recreational amenity











Sheet Pile Dam-Grouted Boulder Structure



2010 and 2011- High Flows cause damage to the grouted boulder structure











Sheet Pile Dam-Grouted Boulder Structure



2014-Grouted boulder structure repaired with two added cross-veins to aid in navigability











Box Culverts



2009-EPA installed two design build box culverts to increase holding capacity of river




































Ecosystem Restoration Emergent Bench













Ecosystem Restoration Challenges and Opportunities





Minimal excavation due to regulated material

- USGS Borehole map to determine where could excavate
- Toe protection and RipRap in areas unable to excavate











Challenges and Opportunities



Jan 8 2009 Flow (Q) 30 cfs



May 4 2009 Flow (Q) 1080 cfs

Highly Managed River

- Utah Lake Compromise (1985)
- Tributaries
- Canals
- Point Sources
- Stormwater (MS4)
- Nonpoint Sources
- Diversions
- Multiple jurisdictions and entities











Challenges and Opportunities



Vegetation Establishment

- Drip Irrigation
- Native upland and riparian vegetation
- Weed mapping and mitigation



- Soil Survey
- Beaver fencing











Drop Structure Site- Emergent Bench













Drop Structure Site- Emergent Bench













Midvale 4th Grade Stewardship Project













Midvale 4th Grade Stewardship Project














Midvale 4th Grade Stewardship Project
















Development of Site















Recreation on the Jordan River














Recreation on the Jordan River











Recreation on the Jordan River













Questions?











